FITNESS CERTIFICATE

1. NAME OF SCHOOL

2. NAME OF OFFICER

3. LOCATION

4.PERIOD FOR WHICH THE CERTIFICATE IS ISSUED

5.CLASSIFICATION OF BUILDING

:CHINMAYA VIDHYALAYA HSS, TC-29/1720,VAZHUTHACAUD

: LEENA R S, Assistant Engineer

: Vazhuthacaud

: 2025-26 Academic year

:RCC Three Storied Main building

45.78X8.30X3m(GF), 45.78X8.30X3m(FF),

45.78X8.30X3m(SF)

Office building-RCC Three storied

7.80X4.50X3m(GF), 7.80X4.50X3m(FF),

7.80X4.50X3m(SF), 7.80X4.50X3m(Cellar)

2nd building RCC Two storied(Cellar)-15X6.60X3m

GF-15X6.60X3m

3rd building(Nursery Section):RCC Two storied

Building

16.50X18.75X3m(GF), 16.50X18.75X3m(FF)

6. NATURE OF DEFECT IF ANY

a)Foundation and basement : Nil

3 50\3m((Tab

ess action (RCC Two stories)

b)Superstructure : Nil

c)doors and windows : Nil

d) woodwork wrought and putup : Nil

e) Roof : Nil

f) Flooring : Nil

g) Miscellaneous : Nil

7. Any major defects noticed which will renders the building unsafe in any manner: Nil

8. Whether maintenance works have been done properly: Yes

9. whether the structure is sound for conduction classes : Yes , This structure is sound under normal

Wind and weather conditions.

1) The stability of the structure should be examined also with reference to the location , altitude, intensity of wind , exposure to flood etc.

2) Any additional observations if deemed necessary for certificate may be furnished separately with the certificate

Certified that the school was inspected by me on 11-08-2025. and found to be fit to conduct classes for the period 2025-26 academic year for the reasons stated above.

TVM Corporation

Date: 11-8-2015

SIGNATURE

DESIGNATION

LEENA.R. dineer
LEENA.R. dinee